

KS3R642L - CAPABILITY LIST

DATED: 9/5/2025

CW Part Number:	Customer P/N:	Description:	Manufacturer:	Added / Date:	Updated Date:	Removed Date:	Limitations:
8082-1 / -2	320798-1 / -2	Solenoid, Valve Assy	Curtiss Wright	3/7/2008	9/5/2025		Overhaul/Modify
8059-2	3242619	Solenoid Assy	Curtiss Wright	5/12/2009	9/5/2025		Overhaul
18037-1	18037-1	DC Pull Solenoid	Curtiss Wright	3/17/2010			Overhaul
399571-XX	399571-XX	Solenoid, Valve Assy	Curtiss Wright	6/10/2011	1/22/2021		Overhaul / Repair / Mod
3238473-1 / -2	3238473-1 / -2	Solenoid, Valve Assy	Curtiss Wright	4/3/2013			Overhaul
20026299	20026299	Regulator / Relief Valve	Curtiss Wright	7/28/2015			Overhaul / Repair
CW30-10040-1	10030295	Engine Anti-Ice Valve	Curtiss Wright	10/22/2015			Overhaul / Repair
320501-XX	320501-XX	Solenoid, Valve Assy	Curtiss Wright	12/17/2015			Overhaul / Repair / Mod
320115-XX	320115-XX	Solenoid, Valve Assy	Curtiss Wright	1/6/2016			Overhaul / Repair
319625-X	319625-XX	Solenoid, Valve Assy	Curtiss Wright	8/5/2016			Overhaul / Repair
7205984-2 / -3	7205984-2	Solenoid Switch Assembly	Curtiss Wright	12/14/2016	3/14/2019		Overhaul / Repair / Mod
1020945-1	1020945-1	Solenoid Buffer Air Valve	Curtiss Wright	12/19/2016			Mod
1028828	1028828	Solenoid Buffer Valve Assy	Curtiss Wright	11/29/2017			Mod
1023263-1	1023263-1	Solenoid Buffer Valve Assy	Curtiss Wright	4/24/2017			Repair / Mod
1029816	1029816	Solenoid Buffer Valve Assy	Curtiss Wright	3/26/2018			Repair / Mod
150003-4	960.30.01.173	Electric Motor Pump Assy	Curtiss Wright	9/12/2018			Overhaul / Repair / Mod
1023142-2	1023142-2	HPCBV Solenoid Assy	Curtiss Wright	10/2/2018			Overhaul / Repair
CW30-10061-2	960.30.01.174	Electronic Control Module	Curtiss Wright	10/29/2018	4/4/2023		Overhaul / Repair / Mod
1023263-2	1023263-2	Solenoid Buffer Valve Assy	Curtiss Wright	3/28/2019			Repair
1029816-1	1029816-1	Solenoid Buffer Valve Assy	Curtiss Wright	8/6/2019			Repair / Mod
188004-3	960.10.04.206	Hydraulic Reservoir	Curtiss Wright	8/6/2019	11/17/2022		Overhaul / Repair / Mod
200198-1	960.10.04.141	De-Spin Manifold	Curtiss Wright	9/25/2019			Overhaul / Repair
600002-4	959.47.51.129	Brake control Manifold	Curtiss Wright	9/25/2019	4/8/2021		Overhaul / Repair
200197-1	960.10.04.143	Isolation Valve	Curtiss Wright	9/25/2019			Overhaul / Repair
230141-1 / -3	960.10.04.172	Filter Manifold	Curtiss Wright	9/25/2019	4/1/2020		Overhaul / Repair
320800-XX	320800-XX	Solenoid Valve Assy	Curtiss Wright	8/21/2020	7/9/2021		Overhaul / Repair
63001978-1	63001978-1	Electrical Assembly	Curtiss Wright	1/22/2021			Overhaul / Repair

FF-18017 Rev. B 06/08/2023

Page 1 of 2

Accountable Manager: Mark Truesdell

Dated:

Mark Truesdell

9-5-2025

[illegible]